Friday, 01/08/2008 2:37:56 PM **Process Sheet** Julie Lecocq User: : SEAT SUPPORT ASSEMBLY, RH **Drawing Name** : CC-DAR01 Dart Aerospace Ltd. Customer : 40879 - 1 Job Number : D3784044 : 13329 Estimate Number Part Number : D3784 REVB P.O. Number **Drawing Number** S.O. No. : : 01/08/2008 This Issue Project Number : NC : B Prsht Rev. **Drawing Revision** : SMALL /MED FAB Type : 31/07/2008 First Issue Material Each : 08/08/2008 : 40661 Previous Run **Due Date** Written By Checked & Approved By 08-05-19 new issue DD verified by:ec : Est Rev:A Est Rev:B 08-07-18 revB as per dwg DD verified by:EC Comment Additional Product Job Number: Description: Machine Or Operation: Seq. #: PACKAGING RESOURCE #1 PACKAGING 1 1.0 Comment: PACKAGING RESOURCE #1 Pick Packing Kit End Fitting Assembly, RH D3763044 2.0 12.0000 Each(s) Total: 1.0000 Each(s)/Unit Comment: Qtv.: End Fitting Assembly, RH Tube D37701 3.0 12.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qtv.: Tube batch Tube D37703 4.0 12.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: Tube B40714 batch End Fitting Assembly D3763041 5.0 24.0000 Each(s) 2.0000 Each(s)/Unit Total: Comment: Qty.: **End Fitting Assembly**

	*
	•
	,

Process Sheet

CC-DAR01 Dart Aerospace Ltd.

Drawing Name: SEAT SUPPORT ASSEMBLY, RH

nber: 40879

Part Number: D3784044

per:



.q. #: Machine Or Operation:

Description:

6.0

MS21042L3

Nut

Comment: Qty.:

4.0000 Each(s)/Unit Total: 48.0000 Each(s)

Nut

batch: M108764

7.0

Washer



Comment: Qty.:

4.0000 Each(s)/Unit

Total:

48.0000 Each(s)

Washer

batch: m 105793

(or NAS1149D0332J) batch:

8.0

AN52510R20



Comment: Qty.:

4.0000 Each(s)/Unit Total:

48.0000 Each(s)

Screw

Screw

batch: 108559

SMALL & MEDIUM FAB RESOURCE 1



9.0

SMALL FAB

Comment: SMALL & MEDIUM FAB RESOURCE 1

1-assemble as per dwg D3784

SB 08/08/190

08-08-18

****Note 8: Hole "A" is located 5" from the end of D3770-3 tube and must be oriented down****

****Note 8: Hole "B" is located 5" from the end of D3770-1 tube and must be oriented forward****

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP



11.0

PACKAGING

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify wiith Dart part # and batch # using a fine point permanent marker on inside of part and Stock

Location: GA

12.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



			•






D3784-044 SEAT SUPPORT ASSY, RH

NOTES:
1) MATERIAL: N/A
2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.78 lbs

DESIGN HS DART AEROSPACE LTD DRAWN HS HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. B D3784 MFG. APPR. TITLE APPROVED SCALE SEAT SUPPORT ASSEMBLY DE APPR. DATE 08.06.23

	•



	(4)	
		*
		,